

To our valued customers:

It has been brought to our attention that due to tolerances between items supplied by different manufacturers, there could be an intermittent contact between the BNC ground of the supplied probe and the APS230 BNC connector.



At this time, our engineering dept. is working towards a solution. Should you experience such a problem, you can easily solve it by slightly bending the ground connection, as indicated. There is no need to return the unit. We are sorry for any inconvenience

